HAI presents:

Introduction to Helicopter Accident Investigation Course at HELI-EXPO 2013

This one-day introductory course will provide attendees with the basic concepts, practical techniques, and various methodologies essential to helicopter accident investigation. Attendees will learn the essentials of helicopter rotor systems, flight controls, performance variables, flight hazards, and material analysis and characteristics. This course will provide an indepth look at the common causal factors involved in helicopter accidents or incidents. It will address the basic techniques used to investigate an accident or incident such as fracture analysis and aircraft performance topics including anti-torque systems, loss of tail rotor effectiveness, translation and wind effects. It will also include main rotor system characteristics and low G, vortex ring and autorotation, and dynamic rollover and resonance. Registration is available at http://www.rotor.com/Events/HELIEXPO2013. aspx. Seats are limited. On-site registration is based on availability. Desk hours: Friday, Mar. 1 -1:00 P.M. to 5:00 P.M.; Saturday, Mar. 2 through Thursday Mar. 7 – 7:00 A.M. to 5:00 P.M.; and Friday, Mar. 8 – 7:00 A.M. to 1:00 P.M.

Directions: Classroom: Level 2, North Hall, Room TBD.Course Registration Desk: Level 2, North Hall, near Room N253.

Event Details

Sun, Mar 3, 2013 - 8:00 am Las Vegas Convention Center

3150 Paradise Road Las Vegas, NV 89109



Contact: HAI 703-683-4747 education@rotor.com

Select #: EA2546694
Representative Kristin Anderson

A message from the National FAASTeam Manager

Over 10,150 AMTs earned an AMT Award last year. Will you, this year? Sign up for the FAA's safety services at www.FAASafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.